



MERCANTILE MARITIME SOLUTIONS PTE LTD

Company Reg. No. 201419851N

Add: #14-12 International Plaza, Singapore 079903
E-mail: sales@mercantile.sg

Tel : (+65) 6220-4882
Fax : (+65) 6225-4470

JOBS ATTENDED FOR MAIN ENGINE

Sr.no	Make	Type/Mode	Job Scope
1	Akasaka Mitsubishi	6 UEC 37LA	Main Engine Overhauling
2	Akasaka Mitsubishi	6UEC37LA2	Main Engine piston unit overhaul / liner renewal/Bearing inspection/fuel pump Overhaul
3	Main Engine TYPE AKASAKA	7UEC37LA	Main Engine piston overhaul , liner renewal
4	B & W	50 MC	Thrust bearing inspection
5	B & W	L 50 MC	Main Engine Overhauling
6	Cegielski-Wartsila Sulzer,	Type: 6RTA52U.	Main Engine cylinder cover renewal
7	DIESEL UNITED SULZER	RTA 84C	Main Engine Cylinder Head Broken Stud Bolt Extraction
8	DIESEL UNITED SULZER	RTA 84C	Main Engine UNIT DECARBONISATION
9	DOOSAN ENGINE	B&W 6S50MCC	Main Engine Fuel Valves Reconditioning
10	DU Sulzer	7 RTA 62	Main Engine piston overhaul, bearing inspection
11	Hanmi Hydraulic Machinery co ltd	VTU – 1100N	Main Engine Injector Testing
12	Hanshin diesel	6L35 MC B & W	Main Engine Piston overhaul, bearing inspection, fuel pump overhaul, liner renewal
13	HITACHI – MAN B&W	6S50MC	Unit overhaul & bearing inspection
14	HITACHI – MAN B&W	S50MC	Main Engine Unit Overhauling with Cylinder Liner
15	HITACHI – MAN B&W	7S80MC-6	M/E Fuel Valve Renewal
16	HITACHI – MAN B&W	6S50MC	Inspection of Main Engine general condition
17	HITACHI – MAN B&W	8L35MC – 6	Inspection of Main Engine general condition
18	HITACHI – MAN B&W	7S80MC-5, H3641	CAMSHAFT COUPLING BOLT INSPECTION
19	HITACHI – MAN B&W	7S70MC-C	STUFFING BOX Main Engine
20	HITACHI – MAN B&W	7S50MC-6	Check F.O. Pump timing.
21	HITACHI – MAN B&W	7S70MC-C	STUFFING BOX Main Engine
22	HITACHI – MAN B&W	7S50MC-6	Inspection of Main Engine general condition (At Surabaya, Indonesia)
23	HITACHI – MAN B&W	7UEC85LSII	Main Engine #6 Exhaust Valve Renewal
24	Hyundai Man B W	5S 60 MC	Main Engine piston overhaul & renewal
25	IHI Sulzer Diesel Engine	7RTA 58	Main Engine Fuel Pump
26	KHI 2SA12	2SA12	Main Engine Crack Repair
27	KOBE DIESEL MITSUBISHI	6UEC52L	Main Engine condition checks
28	MAK	MAK 522C	Main Engine Piston overhaul, bearing inspection, fuel pump overhaul, liner renewal
29	MAK	6M 552C	Main Engine single unit piston over haul
30	MAK	6M552 C	5 unit Piston overhaul
31	MAN 16/24	16/24	Main Engine Overhauling
32	MAN 16/24	16/24	M/E Exhaust Valve Cage
33	MAN B & W	6 L 35 MC Mark 6	Main Engine overhaul and bearing survey
34	MAN B & W	6 L 35 MC Mark 6	03 unit, Fuel pump overhaul



MERCANTILE MARITIME SOLUTIONS PTE LTD

Company Reg. No. 201419851N

Add: #14-12 International Plaza, Singapore 079903
E-mail: sales@mercantile.sg

Tel : (+65) 6220-4882
Fax : (+65) 6225-4470

JOBS ATTENDED FOR MAIN ENGINE

Sr.no	Make	Type/Mode	Job Scope
35	MAN B & W	7 S 80MC	Piston overhaul 3 units
36	MAN B & W	7 S 80MC	5 units piston overhaul
37	MAN B & W	6L50MC	4 unit piston overhaul
38	MAN B & W	7 S 80MC	2 unit piston overhaul
39	MAN B & W	7 S 80MC	Fuel Pump overhaul & timing
40	MAN B & W	7 S 80MC	5 units piston overhaul
41	MAN B & W	6L67 GB	Main Engine unit overhaul & bearing inspection
42	MAN B & W	7 S 80MC	Main Engine 2 unit piston overhaul
43	MAN B & W	7 S 80MC	Main Engine Shock absorber attendance
44	MAN B & W	80MC	Unit overhaul 1 unit
45	MAN B&W	6S42MC MK-6	Main Engine piston unit overhaul, bearing inspection
46	MAN B & W	7S 80MC	Main Engine piston unit overhaul / liner renewal/Bearing inspection/fuel pump o/h
47	MAN B & W	9 L 90GF	Main Engine piston overhaul
48	Kobe diesel	8UEC60LS	Main Engine piston overhaul
49	Main Engine 83SEIL	T 83SEIL	Main Engine Turbocharger No. 3 Inspection
50	Mitsubishi	7UEC85LS II	Main Engine Bearing renewal
51	Mitsubishi	MHI 8UEC75LSII	M/E Overhauling
52	Mitsubishi	MAC-25B	Main Engine JACKET COOLING WATER INLET/OUTLET END COVERS
53	MITSUI B & W	6S60MC-C	Main Engine Overhaul and Auxiliary Overhauling
54	MITSUI B & W	7S60MC	Supervision at Malta Shipyard for Main Engine overhaul
55	PIELSTICK	12PC2.5V400	Main Engine unit overhaul
56	Royce-Marine AS,	Bergen Diesel BRM - 8	Main Engine Piston overhaul, bearing inspection, fuel pump overhaul,
57	STX-MAN B&W	6S50MC-C	Main Engine Overhauling
58	STX-MAN B&W	8S 35ML	Main Engine unit overhaul
59	STX-MAN B&W	6S35MC-MK-7	Main Engine unit overhaul
60	Sulzer	RTA 72	Unit overhaul 5 unit
61	Sulzer	RTA 62	Bearing Inspection (Cross head, main bearing & crankpin)
62	Sulzer	11 RTA96	cross head bearing inspection
63	Sulzer	11RTA 96C	Fuel Pump timing
64	Sulzer	6AL20/24	5 units fuel pump overhaul /timing
65	Sulzer	RTA 84M	1 unit piston overhaul
66	Sulzer	6AL20/24	Main Engine unit overhaul
67	Sulzer	7RTA 620	Main Engine unit overhaul
68	Sulzer	6RTA 72	Cylinder head damaged stud removal & renewal
69	Sulzer	RLB66	unit overhaul, liner renewal, charge air cooler cleaning
70	Sulzer	6 RTA 52 U	Main Engine piston overhaul & liner renewal
71	Sulzer	RLB66	Main Engine Piston unit overhaul,
72	Sulzer	6 RTA 52 U	Main Engine piston overhaul & liner renewal



MERCANTILE MARITIME SOLUTIONS PTE LTD

Company Reg. No. 201419851N

Add: #14-12 International Plaza, Singapore 079903

E-mail: sales@mercantile.sg

Tel : (+65) 6220-4882

Fax : (+65) 6225-4470

Sr.no	Make	Type/Mode	Job Scope
73	Ulstein Bergen	KRG-6	Main Engine Generator Overhauling
74	Wartsila	SL46F	M/E Piston Unit Overhauling and Bearings Survey
75	Wartsila	6L26	Piston overhaul all units
76	Wartsila	12 V38	Main Engine unit overhaul
77	Wartsila	W16 V 32	Main Engine unit overhaul , Liner renewal, Fuel pump overhaul
78	Yanmar	6N330EN-	Main Engine Piston overhaul, bearing inspection, fuel pump overhaul, Honing of liner
79	Yanmar	6RY17P-GV	Main Engine Decarbonisation